


NOTE: THIS IS NOT A FIELD SURVEY. EXISTING
 CONDITIONS MAP IS COMPILED FROM VARIOUS
 CONSTRUCTION DOCUMENTS, AS BUILTS & AERIALS



EXISTING CONDITIONS MAP

NEWINGTON TOWN HALL

NEWINGTON, CT

JUNE 1, 2015

KAESTLE BOOS
 associates, inc

2015 © COPYRIGHT KAESTLE BOOS ASSOC., INC.