



Newington Public Schools







# Main Entrance



- No secondary form of security
- No glass between the doors
- Poor installation

# Nurse's Office



- Not ADA accessible
- Nurse can not see students from his/her office desk
- Poor equipment (sink) placement



# Connector Hallway

- Worms and other insects regularly enter the building



# Hallway Restrooms



- **Glass door does not ensure safety/security**
- **Sinks do not run well**
- **Bad soap dispensers**
- **Lack of bathroom stalls**

**ADA Compliant Bathrooms are not accessible without a long travel distance.**



**Employee bathrooms limited  
and not ADA Compliant.**



**Uneven carpeting throughout the building  
danger to staff and students.**



- **No glass covering to fire extinguisher/ Safety Risk**
- **Chipped water fountains / Safety Risk**





- Windows do not stay up or are hard to open
- Doors do NOT lock properly without force(security issue)
- Insects enter the building due to age of building/access points



- **A/C Heaters do not work properly**
- **Unsafe placement of this equipment, too accessible to students**





- **Open space which could be used for other things**
- **Suspicious growths, water damage beneath the overhang**



- Lack of adequate storage areas
- Inappropriate use of classroom space as well as other areas/closets for storage
- Potential hazards to students and staff



# PA systems do not work properly



**Cracks in walls throughout the school.**





**Inadequate storage closets.**



## Holes, broken cement and tiles throughout the building



- Water damaged ceilings and floors
- Pipes are exposed
- Pipes leaking

## Gymnasium Area





## Storage Area Off Gymnasium

- Uneven/makeshift flooring
- Poor storage of regularly used equipment
- Safety Risk



# Mechanical Rooms

- No A/C
- Rusting
- Mildew-poor air circulation
- Mechanicals in need of Replacement/Upgrades





- **Gym Office Areas in very poor condition**
- **Uneven Flooring**
- **Exposed pipes**
- **Poor Air Quality**



- Not stationary
- Table is not at chair length
- Awkward/ poor placement

## Main Office Reception Area



## Kitchen Area in need of updating



- **Exposed fixtures/Safety Risk**



- Stage lights do not work
- New Stage is needed
- No A/C
- Used for lunch and many events

# Cafetorium

